
Various Coupon Designs

Fig 1(a). Rectangular disbondment with a holiday defect at one end

Fig. 1(b). A circular disbondment with a small gap and a crack in the middle



9




Fig 1©. Disbondment along overlap of a spirally wound tape coating and a holiday at one section




Fig. 2





Fig. 3






Fig. Sa

F17. Sb




Figure 6. Test 1 polarization and pH data collected under a coating disbondment and adjacent exposed defect.




Figure 7. Test 2 polarization data collected at an exposed defect and under an adjacent coating disbondment.